

SMOKE DETECTOR DAMAGE STOPPER®

Super tough protection for smoke detectors where abuse is severe

There's no longer any reason to risk malfunction of your critically important smoke detectors from accidental or intentional damage. This Stopper is easy to install in areas where severe vandalism or physical abuse is causing false fire alarms or high maintenance costs. There are two models to fit virtually all smoke detectors, STI 8100 for flush mount and the STI 8130 with a spacer for surface mount.

Backed by a lifetime guarantee

Because they're moulded of polycarbonate material in a highly durable design, these protective covers carry a lifetime guarantee against breakage in normal use. They are easy to remove for servicing and tamper-resistant hardware is available.



STI 8100



MECA



Features

- Appealing appearance.
- Easy installation and easy removal for servicing.
- Recommended for correctional facilities with smoke detector abuse.
- UL listed for ceiling and wall mount applications.
- Backplate available for mounting on unstable surfaces.
- Models (with spacers) fit virtually all smoke detectors available today.
- Smoke detector's L.E.D. remains clearly visible.
- Tamper-resistant hardware available.
- Factory Mutual System approved.
- Lifetime warranty against breakage in normal use.



Dimensions and Technical Information

Models Available

- STI 8100** Flush mount Damage Stopper with mounting hardware.
- STI 8130** Surface mount Damage Stopper, STI 8100, STI 8101 conduit spacer and mounting hardware.
- STI 8101** Stackable two inch conduit spacer (included with STI 8130).
- STI 8170** Mounting backplate for flush and surface mount models. Recommended for irregular and unstable mounting surfaces such as drop ceilings and beams.
- SUB 81** Tamper resistant mounting hardware kit for use with STI 8100 (four spanner screws).
- SUB 82** Tamper resistant mounting hardware kit for use with STI 8130 (four spanner screws).
- 19038** Tamper bit for SUB 81 and SUB 82.

Testing Approvals

It has been tested and listed by:

- Underwriter Laboratories No. 85Y2 (No sensitivity adjustment needed for Sentrol 611UD, 612UD, 721UD and 731UD only).
- Factory Mutual System
- California State Fire Marshal No. 7300-1416:101

The following drawings show internal unit dimensions.

